


SPHERE & SPHERE BIG

INSTALLATION SHEET

TYPE:

PROJECT NAME:

sphere & sphere big



sphere 1



white / white painted
black / white painted

T46H1IWL
T46H1IZL

sphere big 1



white / white painted
black / white painted

T46H4IZL
T46H4IWL


sphere 3



white / white painted
black / white painted

T46H2IWL
T46H2IZL

sphere big 3



white / white painted
black / white painted

T46H5IWL
T46H5IZL

sphere 7



white / white painted
black / white painted

T46H3IWL
T46H3IZL

sphere 7 big



white / white painted
black / white painted

T46H6IWL
T46H6IZL

INSTALLATION SHEET

tossB[®]

A **Luminart** BRAND

WWW.TOSSBLIGHTING.COM

Last updated: 3/6/20

SPHERE & SPHERE BIG

INSTALLATION SHEET

TYPE:


PROJECT NAME:

SUSPENDING THE SPHERE

SUSPEND THE SPHERE AND ADJUST AS REQUIRED.

WIRING AND CANOPY INSTALLATION

- A- ADJUST THE POWER CABLE LENGTH TO POSITION. CUT THE CABLE SURPLUS.
- B- RAISE THE CROSSBAR AGAINST THE CEILING AND FASTEN TO THE JUNCTION BOX USING (2) MOUNTING SCREWS.
- C- MAKE ALL NECESSARY CONNECTIONS (**FOLLOWING WIRING DIAGRAM AND POLARITY MARKING**) USING THE TWIST CONNECTORS (NOT INCLUDED). MAKE THE CONNECTION FIRST AND INSTALL THE CROSSBAR AFTER.
- D- PLACE THE CANOPY OVER THE CROSSBAR AND SECURE ASSEMBLY IN PLACE WITH (2) SCREWS.



INSTALLATION SHEET

General installation and maintenance directives concerning factory guarantee. Connecting and testing the lamps must always happen by an acknowledged electrician according to the locally applying regulations on electric installations. Do not place on a flammable surface.

tossB®

A **Luminart** BRAND

WWW.TOSSBLIGHTING.COM

Last updated: 3/6/20